

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	1466	(60/752-760).CCLS.	USPAT; USOCR	OR	OFF	2005/11/02 15:01
L2	1633471	(chute\$2 or tube\$3 or dilut\$5)	USPAT; USOCR	OR	OFF	2005/11/02 14:35
L3	655	1 and 2	USPAT; USOCR	OR	OFF	2005/11/02 14:34
L4	98722	(chute\$2 or (tube\$3 near5 dilut\$5))	USPAT; USOCR	OR	OFF	2005/11/02 14:38
L5	66	1 and 4	USPAT; USOCR	OR	OFF	2005/11/02 14:54
L6	3289	((60/39.37) or (60/804) or (60/737-748)).CCLS.	USPAT; USOCR	OR	OFF	2005/11/02 14:54
L7	101	6 and 4	USPAT; USOCR	OR	OFF	2005/11/02 14:54
L8	67	7 not 5	USPAT; USOCR	OR	OFF	2005/11/02 14:54
L9	565	((60/752) or (60/754)).CCLS.	USPAT; USOCR	OR	OFF	2005/11/02 15:01
L10	459	((60/752) or (60/754)).CCLS.	USPAT	OR	OFF	2005/11/02 15:24
L11	1949	(stress\$5 near7 concentrat\$9) with weld\$9	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/11/02 15:25
L12	44	11 same (combust\$9 or burn\$5)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/11/02 15:34
L13	104113	(gas or combust\$7) near3 turbine\$2	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/11/02 15:25
L14	14	12 and 13	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/11/02 15:25
L15	30	12 not 13	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/11/02 15:36

L16	48	11 and 13	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/11/02 15:36
L17	34	16 not 12	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2005/11/02 15:36